



Technical Bulletin

December 30, 2009

BROADCAST ELECTRONICS TECHNICAL SERVICES

Recipients of this Technical Update receive notices from BE Customer Service on product updates and other information for users of BE equipment.


BE SUPPORT

Radio Transmitters & RF Products

Tel: 217.224.9617
rfservice@bdcast.com

STX LP TRANSMITTER POWER SUPPLY MOTHERBOARD UPGRADE

On December 30th, 2009, Broadcast Electronics released a new revision (rev B) of the STX LP power supply motherboard.



The upgraded power supply motherboard will provide an improved level of performance for the primary interface between the main power supply and power amplifier assembly at elevated temperatures and at maximum output power.

All units shipped from Broadcast Electronics after December 30, 2009 will include the upgraded power supply motherboard.

If you are a current STX LP owner, Broadcast Electronics will make a replacement power supply motherboard available free of charge. Contact the RF Technical Services department by phone at 217.224.9617 or e-mail rfservice@bdcast.com and request the 919-4090 STX LP power supply motherboard.

The on-line [STX LP PS Motherboard Replacement Application Guide](#) will provide upgrade assistance.

BE's new STX LP becomes the first low power transmitter to effectively combine the quality, features and support you want at an exceptional value. The STX LP includes an integrated exciter, scalable design, redundant backup controller, IP connectivity, HD Radio compatibility and more, all at an attractive price!

Thank you for choosing Broadcast Electronics!
www.bdcast.com

Broadcast Electronics, Inc. [Legal notices](#)